During the past week, all people who wern't committed on road or bridge projects, or at Ea st Field working on the artillery implacements, were put to work giving A Company a new look.

The a rea hit the hardest was the reads. Because of poor draina ge, the roads became rivers and then quagmires with every rain. A grader and operator were borrowed from D Company, Solith Engr Bn (Const) and were put to work digging out the existing drainage ditches. In no time flat all the ros ds were in a state of shambles and it was nearly impossible to get anywhere on the compound. After much grader and dozer work the roads were restored to the passable state. The s ituation was then reviewed by CPT David A. Corbett. Commanding Officer of A Compa ny, and First Sergeent Lin T. Lau and it was deceided that the present dra inage ditches wern't located in the best spots for proper dra ina ge. The roads were once more destroyed for progress. The new system of ditches bisected some of the present roads so crews had to be set up to cons truct culverts, most of which had to be box culverts due to the lack of eighteen inch steel culvert in the area. After the culverts were put in p la ce, the reads were repaired and over the worst sections of road, base course was spread in an attempt to stabilize the s urface of the road. With the road surfaces repaired. the only rema ining problem was a human one. The drivers in the company just couldn't keep from running over and destroying the head-walls on all the newly installed culverts. This problem is being taken care of by more cautious driving due to the fact that anyone observed driving over the head-walls will spend that evening repairing or replacing it. So a word to the wise, when driving in A Company, watch out for their

culverts or you may be there longer than you planned.